

## UTAH 3809 COMPLIANCE INSPECTION REPORT

*Contract:* U-68571/87994

*Field Office:* UTC030

*Operator(s):* ThirstyStone Resources Inc. (Carl White 520 623-3117)/Chamberlain Stone

*Project name:* Picture Spring Quarry (Picture Spring Claims 1 and 2)

*Location:* T41S R14W Sec 23 NENE

*Disturbance:* Approximately 1.5 acres disturbance

*Hazardous Materials on Site:* None/The site is fairly stable.

*Comments:* Quarry in liesegang banded sandstones in the Shinarump Member of the Chinle Formation. Plan is to reclaim by contouring to slope and fill in pit potentially with trespass stockpile in Harrisburg or with the remaining boulders where practicable. Chamberlain Stone has removed some scattered excavated stone for landscape boulders. Inspection with UDOGM –Lynn Kunzler found reclamation work not acceptable by both BLM and UDOGM. Thirstystone started reclamation work last week but will come back 11/23/2010 to complete (Ryce Foster (602 820 1228).

*Instructions to Operator:* Remove rock berm, blend rock-soil and contour to slope.

*Recommended Action(s):* None.

*Photographs Taken:* See Photographs below.

*Date of Inspection:* October 13, 2010

*Inspector:* Russell Schreiner

Reviewed by: \_\_\_\_\_  
FM, St.George Field Office

Date: \_\_\_\_\_

RECEIVED

OCT 25 2010

DIV. OF OIL, GAS & MINING





Overview of the quarry reclamation from the north edge of the pit, looking down toward the stream.





Overview of the quarry reclamation from the west edge of the pit, looking down toward the stream.





View of the area above the pit after reclamation work. Instructed operator to remove all rubble and the rock berm area into the pit and contour to slope. Some landscape boulders to be left for later removal or used by Thirstystone.





View looking north of the area above the pit after reclamation work. Instructed operator to remove all rubble and the rock berm area into the pit and contour to slope. Some landscape boulders to be left for later removal or used by Thirstystone.